Cariel No.	Department	Faurinment.	Lacation		مماء ماما	
OPGC Serial No.	Department	Equipment	Location	Job description "Cleaning of drains/culverts/water passage inside main plant area at ITPS"		
	Civil Maintainance, Main Plant	NA	ITPS			
Analysis Done by (EIC/Supervisor/Competen t Person)	Signature	Reviewed & Approved by (SIC)	Signature	Date of Issue	Date of revision	Revision No
	DI DI COLO A I	T	HAZARD TEX			T
PHYSICAL HAZARDS	PHYSICAL HAZARDS	PHYSICAL HAZARDS	ELECTRICAL HAZARDS	CHEMICAL/ GAS HAZARDS	EXCAVATION	OTHERS
Noise	Fall from height	Force (Push/Pull)	Shock/ Electrocution	Flammable/ Explosive	Collapse/Sliding	Fire
Radiation	Fall (Slip/Trip)	Caught in/on or between	Static electricity	Fumes Inhalation	Underground live cable damage	Heavy Wind/Rain
Confined space	Fall down/below	Struck by/against	Arc/flash blast	Ingestion/Absorption	EGRONOMICS	Dust exposure
·	Fall of Objects from height		BIOLOGICAL HAZARDS	Body/Eye Contact	Poor Posture	Oil spill
Contact with Hot surface - I	Contact with moving parts	Poor illumination	Snake/Insect bite/Virus infection	Spillage	Repeatative motion	Human factor
PPEs to be used	Safety Helmet,safety G	Glass,Handgloves,Earplug,& safety shoe, .				
Tools required	Phauda,chiesel,trowel,	crowbar etc				
SEQUENCE OF BASIC STEPS		SAFETY, HEALTH & ENVIROMENT		SAFE JOB STEPS AND CONTROL MEASURES		
Cutting & cleaning of silt,earth,graaes,dry stems & leavs from drain.				Clean the site properly. 2) Use safety shoes, safety glass, dust mask, hand gloves. Strike the area by wooden bullah or rake ande drive the snake away if present.		
Emergency Safety measure	s for the job if any-			•		
Applicable Emergency Safety Measures				Emergency Tel Nos- Fire- 777, 222257, Ambulance- 248/277, Hospital-660(Mcr/233//244/222222)		
Overal risk Category- (High	/Modium/Low):	Medium				